

HomeBuyers Inspections PO Box 3454 Manuka ACT 2603

Phone: 02 6260 6260 Facsimile: 02 6260 6262

www.homebuyersinspections.com.au

admin@homebuyersinspections.com.au

# Standard Building Report Pamela Steele Sherpa



# 8 LA TROBE CLOSE PALMERSTON

Vistarison Images Pty Ltd ABN 85 008 662 708



#### STANDARD BUILDING REPORT

PREPARED FOR - Pamela Steele Sherpa

**REFERENCE** - 213090751

PROPERTY ADDRESS - 8 La Trobe Close, Palmerston

**DWELLING DESCRIPTION** - House

STOREYS - Single Level

EXTERNAL WALLS - Brick Veneer

ROOF COVERING - Concrete Tiles

**GROSS LIVING AREA** - 127 m<sup>2</sup> (approximate)

**ESTIMATE AGE** - 21 years old

**ENERGY RATING** - 3.5 Stars

AUTHORISED INSPECTOR - Angus Reid

This report is issued on behalf of the above-mentioned authorised inspector in accordance with AS 4349.1 - 1995 and AS4349.3 - 1998.

Professional Indemnity Policy Number 62CON7129915 expiry date: 10 June 2014.

The report is made after due consideration of the age and construction of the building and is based on a visual inspection only.

This report includes a Structural Pest Inspection Report; an Asbestos Audit is not included.

This report is signed on behalf of:

Per

Angus Reid

Date inspected: 17 September 2013



#### COMPLIANCE AND RELIANCE STATEMENTS

Within 7 days after the day the report is prepared Homebuyers Inspections will provide the following information to the Territory for inclusion in a publicly available register: (our Office operates the Public Register).

- 1. The street address of the residence the report relates to;
- 2. The type of report prepared; (pest or building and compliance);
- 3. The inspection date;
- 4. The name of the inspector who conducted the inspection;
- 5. The name of the business with which the inspector is employed or contracted.

The person who prepared the report or Homebuyers Inspections may give a copy of it, on payment of a reasonable charge, to a person who has entered into a contract to purchase the property.

Reliance may only be placed on this report by the person, who obtained and paid for the report and, in the circumstances provided for in the legislation, by any person who has entered into a contract to buy the property. No reliance may be placed on this report for any contract entered into more than 180 days after the date of the inspection.

#### STANDARD BUILDING REPORT

#### **FOR**

#### 8 LA TROBE CLOSE, PALMERSTON

#### PROPERTY DESCRIPTION

A brick veneer residence with concrete roof tiles on a trussed softwood roof frame with concrete floors.

Accommodation includes three (3) bedrooms, lounge/living room, dining room, family room, bathroom, toilet, laundry, kitchen, detached garage and attached carport.

#### **GENERAL SUMMARY**

Walls: The walls throughout the property are in good structural condition.

Ceilings: The ceilings are in sound condition throughout with no excessive

sagging or significant water damage evident.

Floor: The concrete floor slab is generally concealed by floor coverings

however there were no defects evident.

**Roof:** The roof frame is constructed from prefabricated roof trusses and is

in a sound overall condition. The roof tiling is in a sound condition.

Summary: The residence is in a sound condition for its age.

#### INTERNAL APPRAISAL

Some of the positive remarks in this report may seem repetitive and are included purely to let you know the particular area was found acceptable

Entry This area was found to be in acceptable condition with no

significant defects evident.

Hallway This area was found to be in acceptable condition with no

significant defects evident.

Lounge Room This area was found to be in acceptable condition with no

significant defects evident.

**Dining Room** This area was found to be in acceptable condition with no

significant defects evident.

Family Room This area was found to be in acceptable condition with no

significant defects evident.

Kitchen This area was found to be in acceptable condition with no

significant defects evident.

Main Bedroom This area was found to be in acceptable condition with no

significant defects evident.

Bedrooms 2,3 These areas were found to be in acceptable condition with no

significant defects evident.

Bathroom This area was found to be in acceptable condition with no

significant defects evident. The shower base has been run and filled with water to check for leakage. No leakage was evident at

the time of the inspection.

Toilet This area was found to be in acceptable condition with no

significant defects evident.

Laundry This area was found to be in acceptable condition with no

significant defects evident.

## MAINTENANCE REPORT

#### **INTERNAL**

#### Bathroom

• There are a few chips to the bath enamel.

#### Miscellaneous

- Appliances (such as ovens, microwaves, dishwashers, spa motors, furnaces, air-conditioning units etc) have not been tested.
- All internal water taps, toilet, showers etc were operated successfully.
- Windows, which were not locked, were checked for ease of operation and found to be generally in working order.

#### EXTERNAL APPRAISAL

Some of the positive remarks in this report may seem repetitive and are included purely to let you know the particular area was found acceptable

Front Elevation Fascias, eaves and mouldings are in acceptable condition. The

brickwork has no significant movement or settlement cracks indicating the foundations and footings are adequate and stable.

**Right Elevation** Fascias, eaves and mouldings are in acceptable condition. The

brickwork has no significant movement or settlement cracks indicating the foundations and footings are adequate and stable.

**Left Elevation** Common boundary.

**Rear Elevation** Fascias, eaves and mouldings are in acceptable condition. The

brickwork has no significant movement or settlement cracks indicating the foundations and footings are adequate and stable.

**Roof Space** The roof frame is constructed from prefabricated roof trusses

and is in a sound overall condition. There are insulwool batts

installed in the ceiling space.

**Roof** The roof tiling is in a sound condition.

Garage/Carport The garage is in an acceptable condition throughout.

The carport is in an acceptable condition.

Fencing and Gates The fences are in a sound condition for their age.

# MAINTENANCE REPORT

## **EXTERNAL**

Right Elevation

• The hot water service is a 6 year old, 130 litre gas unit in working order.

# STRUCTURAL PEST INSPECTION FOR

## 8 LA TROBE CLOSE, PALMERSTON

The areas inspected were

Exterior, interior, roof void, fences and grounds (post stumps and

trees).

The areas not inspected were

Wall cavities were inaccessible.

Internal There was no evidence of structural pest infestation (termite,

borer) internally.

Roof Space There was no evidence of structural pest infestation (termite,

borer).

Fencing There was no evidence of structural pest infestation (termite,

borer).

Outbuilding There was no evidence of structural pest infestation in the garage

or carport.

General No visual termite or other structural pest activity was found during

the inspection.

This report is confined to the reporting of the discovery or non-discovery, as the case may be, of the present or past infestation of Subterranean Termites, Borers, Wood Decay Fungi or Mortar Bees (herein after referred to as "Structural Pests") by visual inspection of those areas and sections of the property accessible to the Inspector on the date of the inspection. The inspection did not cover any other pests and this Report does not comment on them. Nothing contained herein implies that any inaccessible or partly inaccessible areas or sections of the property being inspected by the Inspector on the date of the Inspection were or were not or have or have not been infested by Structural Pests. This report is not a guarantee that an infestation or damage does or does not exist, nor is it a guarantee that a future infestation of Structural Pests will not occur or be found.

If past or present Termite activity and/or damage is found then damage may exist in concealed timbers such as wall framing, which cannot be determined without further exploration work.

No inspection was made of any areas concealed by wall linings or sidings, soil, landscaping, rubbish, floor coverings, furniture, pictures, appliances, stored items, insulation, masonry, hollow posts or any other obstructions to visual inspection. No inspections of any furnishings or household items were made.

#### COMPLIANCE REPORT

## **BLOCK 8 SECTION 125 PALMERSTON**

As requested a detailed inspection of the documents provided by ACT Planning and Land Authority was undertaken on 17 September 2013.

A summary of details found on file and the subsequent on site inspection relating approved drawings to the property follows:

#### **Document Register**

Building Approval Plan No.	Certificate of Occupancy No.	Date of Certificate of Occupancy	Description of Works		
78806/A	10251	9/7/92	New Residence		
78806/B	24122	15/11/93	Carport		
78806/C	38441	28/11/95	Metal Garage		
976276/A	976276P1C1	13/1/98	Addition		

#### **Summary**

The developments of the property have been generally built in accordance with the approved plans as listed on the document register. Certificates of Occupancy have been issued as required for all work undertaken.

The Survey Certificate indicates no encroachments. Easements are clear of encroachments (garden sheds are not commented on due to their lightweight, portable nature).

This Compliance Report is based on documents provided by the ACT Planning and Land Authority and deals with matters as documented on approved plans. Homebuyers Inspections cannot access the building file and is not responsible for omissions made by ACT Planning and Land Authority. It is based on a comparison of the approved documentation with the improvements on the property.

Angus Reid Angus Reids Homebuyers Inspections PO Box 3454 MANUKA ACT 2603

Financial Services Group GPO Box 4189, Sydney NSW 2001 Level 30, Aon Tower 201 Kent Street, SYDNEY NSW 2000 DX 10206, Sydney Stock Exchange Telephone 61 (2) 9253 7000

13 June 2013

To Whom It May Concern,

#### Certificate of Currency

In our capacity as Insurance Brokers to Angus Reids Homebuyers Inspections, we hereby certify that the undermentioned insurance policy is current.

This certificate is issued as a matter of information only and confers no rights upon the certificate holder. This certificate does not amend, extend or alter the coverage afforded by the policy detailed below, or assume continuity of the policy.

CLASS: Professional Indemnity Insurance

Vistarison Images Pty Ltd and/or Angus Reids Homebuyers Inspections INSURED:

4:00 pm on 10 June 2013 PERIOD OF INSURANCE: From

4:00 pm on 10 June 2014

PROFESSION: Pre-purchase building inspections and energy rating using the Bers Pro and

First Rate software

\$1,000,000 any one claim, \$2,000,000 in the aggregate LIMIT OF INDEMNITY:

**EXCESS:** \$10,000 each and every claim

62CON7129915 **POLICY NUMBER:** 

SECURITY: CGU Insurance Limited

ABN 27 004 478 371

Subject to the Terms and Conditions of this Policy.

This certificate of currency has been issued as a matter of information only and does not constitute an insurance contract upon which claims may be made.

Issued by:

Brian O'Mara Service Executive

So- Onlar

Aon Risk Solutions | Corporate Risk Services | Level 33 Aon Tower | 201 Kent Street | SYDNEY | INSW 2000 1+61 2 9253 7009 | | aon com au

#### REPORT DISCLAIMER

This report is carried out in accordance with Australian Standard AS 4349.1-2007.

The purpose of this report is to identify faults and defects within the property and give an indication as to their severity.

Although the property may have pleasing aspects, these have not been addressed within this report.

Specific defects and areas that are considered to require attention have been identified separately within the body of this report.

We would recommend that an identification survey be carried out on this property to assist in determining the boundaries and any associated encroachments by or upon the property.

As our inspection is visual we cannot conclusively state the condition of the foundations. Foundations can be subject to various forms of movement such as wetting and drying causing shrinkage and expansion or earth movement. This manifests in the building fabric by cracking or causing windows and doors not to operate efficiently, hence to fully assess the sub strata on which the building structure rests a geotechnical report is required. Alternatively the Government/Councils may be contacted regarding potential site stability. Local Government/Councils can also advise on local flooding and the adequacy of stormwater reticulation.

Any significant tree within close proximity to the structure may have an influence upon the foundation material/footings and if applicable we would recommend that further advice be sought from an expert.

This property report is not intended as a warranty or an insurance policy against problems developing with the building in the future.

**Note:** The inspection was of a visual nature only and did not involve physical structural testing of any component of the building nor did it involve excavation of the site or removal and testing of any materials upon the site or components of the structure.

This report is an indication of the overall condition of the building with regard to serious defects, and therefore does not address non significant minor details, such as cracked panes of glass, the operation of windows, doors, taps washers, stoves, dishwashers, air-conditioning units and other household appliances and the like (unless otherwise stated).

This report does not and cannot state the extent of any damage. If any Timber Pest activity or damage is noted in this report, it is strongly recommended that a qualified person such as a builder, engineer, architect or other qualified expert in the building trade be asked to determine the full extent of the activity and/or damage to the structure and the extent of the repairs required.

Important Notice: Australian Standard AS 4349 recognises that a standard property inspection is NOT a warranty. To further protect your interests we strongly advise that you consider insuring your house against undetected structural damage and problems developing with the building structure in the future.

# Homebuyers Inspections

# STRUCTURAL PEST INSPECTION CERTIFICATE

This certifies that the property at:

8 LA TROBE CLOSE, PALMERSTON

has been inspected by **Homebuyers Inspections** for


Pest Infestation and subject to the full report completed on 17 September 2013

Authorised by **Angus Reid**Inspection number **213090751** 

Signed:

Date: 17 September 2013

## FirstRate Report





YOUR HOUSE ENERGY RATING IS: \*\*

3.5 STARS

in Climate: 24

SCORE:

-10 POINTS

Sherpa Name:

Block 8, Section 125, Palmerston

17-09-2013

Address:

House Title:

8 La Trobe Close

Palmerston

Reference:

C:\...\PM 125 008 0 00 00 000

**ACT HOUSE ENERGY** RATING SCHEME

Ref No:

Date:

-10 points 3.5 stars

Class A Building Assessor (Energy Efficiency

This rating only applies to the floor plan, construction details, orientation and climate as submitted and included in the attached Rating Summary. Changes to any of these could affect the rating.

#### Appliance Ratings

Unknown Heater / Unknown Rating Heating: Unknown Cooling / Unknown Rating Cooling:

Unknown Hot Water System / Unknown Rating HotWater:

NOTE: The appliance ratings above are based on information provided by the applicant and are included for information purposes only. They do not affect the House Energy Rating of the dwelling.

17-09-13 10:05:51 Ver:4.00 C:\DOCUMENTS AND SETTINGS\ALL USERS\DESKTOP\IST RATE ENERGY RATINGS\PM 125 008 0 00 00 000.1RT

#### IMPROVING YOUR RATING

The table below shows the current rating of your house and its potential for improvement.

	POOR				AVERAGE			GOOD			V. GOOD	
Star Rating	0 Star ★		k	** ***		**	***		****		****	
Point Score	-71	-70	-46	-45	-26	-25	-11	-10	4	5	16	17
Current	-10											
Potential	43										19	

Incorporating these design options will add the additional points required to achieve the potential rating shown in the table Each point represents about a 1% change in energy efficiency. This list is only a guide to the range of options that could be used.

Design options	Addition	nal points
Change ceiling insulation	R 4	3
Change glass to Double Glazing low e	100 %	13
Change frame to	Aluminium-Thermally Broken	15
Change curtain to	Heavy Drapes & Pelmets	22

#### **ORIENTATION**

Orientation is one of the key factors which influences energy efficiency. This dwelling will achieve different scores and star ratings for different orientations.

Current Rating	21	*****
Current Hating	21	*****

Largest windows in the dwelling;

Direction: North East Area: 12 m<sup>2</sup>

The table below shows the total score for the dwelling when these windows face the direction indicated.

Note that obstructions overshadowing windows have been removed from all windows in these ratings to allow better comparisons to be made between orientations.

ORIENTATION	POINT SCORE	STAR RATING
1. North East	-10	***
2. East	-12	<b>★★★☆</b>
3. South East	-15	***
4. South	-17	***
5. South West	-20	***
6. West	-19	***
7. North West	-18	***
8. North	-14	***

FirstRate Mode Climate: 24

RATING SUMMARY for:

Block 8, Section 125, Palmerston, 8 La Trobe Close, Palmerston

Assessor's Nar Net Conditione		a: 109.3 m²						Points	
Feature							Winter	Summer	Total
CEILING		· · . :	ni tara s		1 . 40 1		1	0	1
Surface Area:	0	Insulation:	1						
WALL	****						3	0	3
Surface Area:	-1	Insulation:	4	Mas	\$:	0			
FLOOR							12	0	13
Surface Area:	0	Insulation:		l Mas	s:	13			
AIR LEAKAG	E (Percen	tage of sco	re shown	for each	element)		8 .	O	8
Fire Place	Vented S	Vented Skylights 0 %							
Fixed Vents 0 %			Windows	Windows 53 %					
Exhaust Fans	Doors	Doors 27 %							
Down Lights	0 %	Gaps (are	ound frame		21 %				
DESIGN FEA	TURES 🤄						0	0	0
Cross Ventilation	1	0						d 5 - 22 - 2 - 2 - 2	The easies of the
ROOF GLAZI	NG						0	0	0
Winter Gain		0	Winter Lo	oss	<b></b>	0			
WINDOWS -							-10	-8	-18
Window	А	rea		Point	Scores				
Direction	m2	%NCFA	Winter* Loss	Winter Gain	Summer Gain	Total			
NE	12	11%	-28	20	-3	0	]		
SW	9	9%	-19	5	-2	0	}		
NW	12	11%	-28	10	-3	0			
Total	33	30%	-75	35	-8	-18			

<sup>\*</sup> Air movement over glazing can significantly increase winter heat losses. SEAV recommends heating/cooling duct outlets be positioned to avoid air movement across glass or use deflectors to direct air away from glass.

The contribution of heavyweight materials to the window score is -3 points		Winter	Summer	Total
RATING ****	SCORE	16	-8	21*

<sup>\*</sup> includes 13 points from Area Adjustment

#### **Detailed House Data**

#### **House Details**

ClientName Sherpa

Block 8, Section 125, Palmerston 8 La Trobe Close HouseTitle

StreetAddress Suburb Palmerston FileCreated 17-09-2013

#### Climate Details

State

Canberra Town 2600 Postcode 24 Zone

#### Floor Details

ID	Construction	Sub Floor	<u>Upper</u>	<u>Shared</u>	<u>Foil</u>	<u>Carpet</u>	Ins RValue	<u>Area</u>
	Concrete Slab on ground	No Subfloor	No	No	No	Tiles	R0.0	10.0m²
	Concrete Slab on ground			No	No	Carp	R0.0	110.0m²

#### Wall Details

ID	Construction	Shared	<u>Ins RValue</u>	<u>Length</u>	<u>Height</u>
1	Brick Veneer	No	R1.5	43.0m	2.4m

#### **Ceiling Details**

<u>ID</u>	Construction	Shared	<u>Foil</u>	Ins RValue	<u>Area</u>
1	Attic - Standard	No	No	B2.8	120.0m <sup>2</sup>

#### Window Details

									Fixed &	Fixed	Head to
<u>ID</u>	Dir	Height	Width	<u>Utility</u>	Glass	Frame	<u>Curtain</u>	<u>Blind</u>	<u>Adi Eave</u>	<u>Eave</u>	<u>Eave</u>
ī	SW	1.6m	2,6m	No	SG	ALSTD	VB	Yes	1.6m	0.0m	0.0m
2	NW	2.1m	1.8m	No	SG	ALSTD	VB	No	2.0m	2.0m	0.0m
3	NW	1.9m	1.8m	No	SG	ALSTD	VB	No	2.0m	2.0m	0.0m
4	SW	1.0m	2.0m	Yes	SG	ALŞTD	NC	Νo	4.0m	4.0m	0.0m
5	SW	1.8m	1.8m	No	SG	ALSTD	VB	No	3.0m	3.0m	0.0m
6	NE	1.8m	2.6m	No	SG	ALSTD	VΒ	Yes	2.0m	0.5m	0.0m
7	NE	1.8m	1.4m	No	SG	ALSTD	VΒ	No	0.5m	0.5m	0.0m
8	NE	1.8m	2.6m	No	SG	ALSTD	VΒ	Yes	2.0m	0.5m	0.0m
ñ	NIM	1 8m	2 6m	No	SG	ALSTD	VR.	No	1.5m	1.5m	0.0m

#### Window Shading Details

				Obst	Obst	Obst	Obst	LShape	LShape	LShape	LShape
ID	Dir	Height	Width	Height	Dist	Width	Offset	Left Fin	Left Off	Right Fin	Right Off
2	NW	2.1m	1.8m	0.0m	0.0m	0.0m	0.0m	0.0m	0.0m	6.0m	2.5m
3	NW	1.9m	1.8m	0.0m	0.0m	0.0m	0.0m	0.0m	0.0m	6.0m	0.5m
4	SW	1.0m	2.0m	0.0m	0.0m	0.0m	0.0m	4.0m	0.0m	0.0m	0.0m
7	NE	1.8m	1.4m	0.0m	0.0m	0.0m	0.0m	0.0m	0.0m	6.0m	0.0m
9	NW	1.8m	2.6m	0.0m	0.0m	0.0m	0.0m	6.0m	2.0m	0.0m	0.0m

#### Sky Light Details

ID	<u>Dir</u>	<u>Till</u>	<u>Type</u>	<u>Shade</u>	<u>Utility</u>	<u>Width</u>	Length
1	SW	15 degrees	Single Clear	No	Yes	0.4m	0.4m

#### Zoning Details

Is there Cross Flow Ventilation? Average

#### Air Leakage Details

17-08-13 10:05:55 Ver:4:00 C::DOCUMENTS AND SETTINGS/ALL USERS/DESKTOP/IST RATE ENERGY RATINGS/PM 125 008 0 00 00 000.1RT

Location	Suburban
Is there More than One Storey?	No
Is the Entry open to the Living Area?	Yes
Is the Entry Door Weather Stripped?	Yes
Area of Heavyweight Mass	0m²
Area of Lightweight Mass	0m²

	Sealed .	<u>UnSealed</u>
Chimneys	0	0
Vents	0	0
Fans	0	0
Downlights	0	0
Skylights	0	0
Utility Doors	0	0
External Doors	2	0
Unflued Gas Hea Percentage of W Windows - Avera External Doors - Gaps & Cracks S	indows Sealed ige Gap Average Gap	0 100% Small Small Yes



# **Building Conveyancing Enquiries and Energy Rating Package Application**

78806

#### About this form

Use this form to request and pay for an Energy Rating Package or Conveyancing Enquiry for either a Residential or Non Residential ACT property with the ACT Planning and Land Authority.

All fields are mandatory unless stated otherwise.



The ACT Government is committed to improving the accessibility of web content. To provide feedback or request an accessible version of a document please phone 13 22 81.

Request Type & Profession	nal User	
Select a request type		
Residential conveyancing en	nquiry	
-	<del></del>	
Are you a Professional User	registered with the ACT Planning and Land Authority?	
Professional User Details		
Professional User ID	<del></del>	
5624607		
Name title (optional)		
Μτ		
Given name	Family name	
Angus	Reid	
Contact phone number		
62606260		
Property Information		
Suburb/District	Section Block Unit (optional)	
PALMERSTON	125 8	
Lessee	Applicant's Reference (optional)	
Sherpa		
If you require help with suburt	b/district, section or block details click this information button	
Address		
8 La Trobe Close		
: Address (optional)		
Suburb	State/Territory Postcode	
PALMERSTON	ACT 2913	
; L		

Location description (optional)
Additional Property Information
If the residence is a former Government residence without alterations or additions, the building plans may not be available.
Is the property an ex Government residence?  OYes  No
Additional Documentation
Please click the appropriate box to include any of the following documentation. Additional fees apply (optional)
Sanitary Drainage Plan 🗵
Priority
Our aim is to provide a 4 to 5 full working day turnaround period for a standard service. The turnaround time commences from receipt of the request at Mitchell and does not include weekends, public holidays or delivery time by mail or DX for professional users. For high priority requests an additional surcharge is applied and the turnaround period is 24 hours with the same conditions specified above.
Our aim is to provide a 4 to 5 full working day turnaround period for a standard service. The turnaround time commences from receipt of the request at Mitchell and does not include weekends, public holidays or delivery time by mail or DX for professional users. For high priority requests an additional surcharge is
Our aim is to provide a 4 to 5 full working day turnaround period for a standard service. The turnaround time commences from receipt of the request at Mitchell and does not include weekends, public holidays or delivery time by mail or DX for professional users. For high priority requests an additional surcharge is applied and the turnaround period is 24 hours with the same conditions specified above.
Our aim is to provide a 4 to 5 full working day turnaround period for a standard service. The turnaround time commences from receipt of the request at Mitchell and does not include weekends, public holidays or delivery time by mail or DX for professional users. For high priority requests an additional surcharge is applied and the turnaround period is 24 hours with the same conditions specified above.  What is the priority of this request?  Standard O High
Our aim is to provide a 4 to 5 full working day turnaround period for a standard service. The turnaround time commences from receipt of the request at Mitchell and does not include weekends, public holidays or delivery time by mail or DX for professional users. For high priority requests an additional surcharge is applied and the turnaround period is 24 hours with the same conditions specified above.  What is the priority of this request?  Standard OHigh  Method of Delivery
Our aim is to provide a 4 to 5 full working day turnaround period for a standard service. The turnaround time commences from receipt of the request at Mitchell and does not include weekends, public holidays or delivery time by mail or DX for professional users. For high priority requests an additional surcharge is applied and the turnaround period is 24 hours with the same conditions specified above.  What is the priority of this request?  Ostandard  High  Méthod of Delivery  Please select your preferred delivery method
Our aim is to provide a 4 to 5 full working day turnaround period for a standard service. The turnaround time commences from receipt of the request at Mitchell and does not include weekends, public holidays or delivery time by mail or DX for professional users. For high priority requests an additional surcharge is applied and the turnaround period is 24 hours with the same conditions specified above.  What is the priority of this request?    Standard  High  Méthod of Delivery  Please select your preferred delivery method  Collect at Mitchell Counter
Our aim is to provide a 4 to 5 full working day turnaround period for a standard service. The turnaround time commences from receipt of the request at Mitchell and does not include weekends, public holidays or delivery time by mail or DX for professional users. For high priority requests an additional surcharge is applied and the turnaround period is 24 hours with the same conditions specified above.  What is the priority of this request?  Standard  High  Method of Delivery  Please select your preferred delivery method  Collect at Mitchell Counter  Collect at ACT Government Shopfront

Applicant Declaration	HANDER!								
As the applicant lodging this request, you are declaring:									
O I am the lessee/owner.									
O 1 am the solicitor acting on behalf of the lessee/owner.	1								
I have authorisation from the lessee/owner.	1								
O I am/act for a mortgagee in possession.									
O I have authorisation from the solicitor representing the lessee/owner.									
I have authorisation from the Trustee of the deceased estate.									
O I have authorisation for power of attorney from the lessee/owner.									
Please Note: 1. Documentation confirming that you have the lessee/owner's permission is required in all instances. Unless you have a "Professional User" ID you must present this written proof when you collect the requested information from the Mitchell Counter. 2. The applicant must comply with one of the above declarations to protect any personal information relating to the lessee/owner of this lease under the provisions of the Privacy Act 1988. 3. Section 59A of the ACT Building Act 1972 provides severe penalties for false or misleading statements.									
Payment amount \$ 104.10									
Receipt									
Your payment has been successful. Please keep a copy of this receipt for your records.									
Date and time 09 Sep 2013 15:31:23									
Form submission ID 34003920130909158587									
Payment receipt number 1259115584									
Total amount paid \$ 104.10									
To save or print a copy of the completed form and receipt go to the "File" menu and select "Save as" or "Print".									
Environment and Sustainable Your personal information will be used for the purposes to completing your Form ID: 1014	7								

Development Directorate ABN 31 432 729 493

GPO Box 1988 Canberra ACT 2601 Telephone: 132281 Your personal information will be used for the purposes to completing your enquiry and will be disclosed to the Environment and Sustainable Development Directorate to achieve that purpose and kept on file. Details about this ransaction will be released to you or your financial institution if this transaction is queried and otherwise will not be disclosed to any third party except in accordance with the Privacy Act 1988 (Cth).

Version: 22

Date: 09 Sep 2013

CONVEYANCING BUILDING FILE INDEX

	INGS				3-92					1-93			-	1-95					2-97	
PAGE: 1/1	FOOTINGS				19-03-92					15-11-93				28-11-95					19-12-97	
PAGE	COU PLAN NO. & DATE						78806/A 09-07-92				78806/8 15-11-93				78806/C 28-11-95					976276/A 13-01-98
No	COST OF WORKS	\$61,121						\$1,897				\$3,400				\$12,800				
EX GOV: No	PERMIT NUMBER			78805/A			•		78806/8				78805/C					976276/A		
1	SURVEY	***************************************				¥														
UNIT:	INDEM		09-03-92														22-08-97	5		
В	DETAILS																			
BLOCK:	AMEND					-														
125	DESCRIPTION OF WORK	Residence				Survey		Carport		Final		Metal Garage		Final		Additions			Final	
SECTION: 125	FOLIO NO.	7	7	6	10	15	24	7.2	31	37	38	39	54	57	58		-	•		
SUBURB: Palmerston	PLAN	78805/A						78806/8				78806/C				976275/A				
SUBURB:	COU ISSUED Y/N	, ,						>-				>-				>-				

Orainage Plan Number: 56539

Comments:

Soil Classification Number: Yes

#### **CONVEYANCING PART 2**

No information is provided in respect of electrical, drainage or sewer matters and or to the location of overhead power lines or underground cables in relation to the building.

	· ·	162	140
1.	<ul><li>(a) Is this a government or ex government house?</li><li>(b) If yes, is there a building file with approvals on it?</li></ul>		
2.	Is there any record of incomplete building work on the building file? See file copies attached		$\boxtimes$
3.	Are there any records on the building file of current housing Indemnity insurance policies for building work? (Current within 5 years) See file copies attached		$\boxtimes$
4.	Are there any records on the building file showing building applications still being processed?  (Current within 3 years) See file copies attached		
5.	Are there any records on the building file of current notices issued over the property? See file copies attached		$\boxtimes$
	If available, copies of the following documents are provided:  Certificate of Occupancy  Survey Certificates  Approved Building Plans  Ex government Building Plans  If requested:		
	Drainage Plan(s)	$\boxtimes$	
	Search officer comments (if any?)  Search officer initials: Keryn  Cost of application: \$ 104.10  Date completed: 13-09-13		

Please Note: Building approvals that have been generated via eDevelopment will be issued with a project number prefixed by the letter 8. Initial building approval documentation will be identified with project number B20XXXXX only but will be referenced as B20XXXXX/A on the Certificate of Occupancy and Use. Any amendments to the original approval will be issued with the project number and an alphanumeric digit. The first amendment will be identified as B20XXXX/B, the second amendment B20XXXX/C etc.

## Surveyor's Certificate

John W. Foxlee (\$12)MII(644) Registered Surveyor

42 Yiman Street, Waramanga, A.C.T. 2611 P.O. Box 472 Manuka, A.C.T. 2603 Telephones: 88 1257 95 9392

Block:

8

Section:

125

Division: PALMERSTON Ti

Title:


The Manager,
Finto Homes Fty. Ltd.,
152 Dumas Street,
MCKELLAR. A.C.T. 2617.

Dear Sir,

I certify having surveyed the land being <u>Block 8</u>, <u>Section 125</u>, <u>Division of FALMERSTON</u> in the Gungahlin District of the Australian Capital Territory, as delineated in Deposited Plan No. X14067 lodged at the Office of the Registrar of Titles, Canberra City. The block has an area of 600 square metres or thereabouts and has a frontage to La Trobe Close,

Upon this land stands the brick foundation of a residence in the course of erection. The position of this brickwork in relation to the boundaries of the land is shown on the sketch plan endorsed hereon.

The building is contained wholly within the boundaries of the land and there are no encroachments by or upon the said land.




# Department of Urban Services ACT Building Control


GPO Box 158, Canberra ACT 2601


24


# Certificate of Occupancy or Use


:	, ,
	٠.
Persuant to Part V of the Building Act 1972, the build	
IEW RESIDENCE	
situated at / Division: / Section: Block: Unit: Palmerston 7 125 8	
s considered to be substantially in accordance with trequirements for occupancy or use, subject to the endo	he prescribed rsements listed below
approved plan id's included in this certificate; A	
Project-Number: 10251 Type of construction: Classes of occupancy: 01 10 Name of Permit Holder: PINTO HOMES PTY LTD	TRIMS Number: 78806
Fit for occupancy or use pursuant S 53[3]	
Endorsements:	•
ador serents.	The state of the s
	·
	•
Mark the Column (1941) and the Column (1941)	
•	•
,	
·	
The issue of this Certificate does not affect the liability of a person to comply with th	ne provisions of a law of the
Territory (including the Swilding Act) relating to the building work nor does it authoris	se the user of the land
contrary to a provision, convenant or condition of lease.	·
<b>\</b> \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	•
9,7.	an
	16.
Deputy Building Controller Date	
$\bigcup \bigcup \bigcup$	















	cuevr PINO HOMES ph: 2581709		DRAWING RUMBER	92664- 4
.		1:00		
	residence Section 125 STON	33		
	mouect proposed resid Block 8 Section PALMERSTON	feb92 scut	S	
	morect proposed Block 8 PALMERS	W W	PAK#	CAECKED

1/6/4E8 1992

, Sibrous cement sheet wall lining to retareas.

1 part lime Mhere Brick plants exceed 1400mm in height bose brickwork is to be 3504359.

Plasterboard mail and ceiling lining.



....,

....




# Department of Urban Services ACT Building Control

GPO Box 158, Canberra ACT 2601

# Certificate of Occupancy or Use


Persuant to Part V CARPORT	of the Baildin	g Acl 1972, (	he building cor	sisting of a	
situated at Division: S Palmerston	ection: 125	Block:	Unit:	•	•
is considered to be requirements for oc	substantially cupancy or use	in accordance, subject to	e with the pres the endorsement	scribed ts listed below:	
Approved plan id's B	included in th	is certificat	.e:		
Project Number: 241 Classes of occupance Name of Permit Hold	y: 10		: TRIMS 1	Number: 78806	
Fil for occupancy o	r และ hแนลแชก <sub>ไ</sub>	. S 53[3]			
Endorsements:	•				
		- pag and sold some and side had been fine to the sold sold sold to the sold sold sold sold to the sold sold sold sold sold sold sold sold		k.	-
	•				_
	. May digay time time, year time and the side of the gain, side side, side	ay. Jinga ganga pang-pang-pang-pang-pang-pang-pang-pang-			_
					_
					_
		•		F	
	/			•	
The issue of this Certificate of Territory (including the Buildi contrary to a provision, convertible).  Deputy Building	ng Act) relating to the ant or condition of ier	; building work nor do use.	comply with the provision as it authorise the user	is of a law of the of the land	,






Proposed Single Carport FOR NEP LATROBE Block & Section 125


PALMERSTON



Note: 30 x 5 FMS Knee Bracing fitted on free standing Carport



PLAN Beam - C10015 for Span to 3.700 RHS Bridging - Mid Span Overhang - 1.000 Font Spacing - 3.500 Footing Size - 300 sq x 460 deep



STAUNCHION TO FRAME

#### SPECIFICATION

FOUNDATIONS: Mixing of concrete shall he in proportion of 4:2:1

4 parts aggregate 2 parts sand

1 part cement COLUMNS: To be set in concrete pads as shown & to be 65 x 65 x 2.8 RHS bolted to roof structure as shown.


ROOF STRUCTURE: To be standard fascia gutter .62 reinforced with 45 x 45 x3 angle as shown. Structure bolted

together with MIO x 25 HH bolts.
ROOF MATERIAL: To be .47 Trimdek Hiten roofing pop rivetted to gutters and fixed to purlins with Tech screws. Provide 51mm or 65mm downpipes and connect to stormwater line as necessary

PAINTING: Fascia gutter & columns to be painted to Departmental approval by others.

GENERAL: Site to be left clean & tidy. All work to be done in a workmanlike manner.








# Certificate of Occupancy or Use

•
Persuant to Part V of the Building Act 1972, the building consisting of a METAL, GARAGE
situated at Division: Section: Block: Unit: Palmerston 125 8
is considered to be substantially in accordance with the prescribed requirements for occupancy or use, subject to the endorsements listed below:
Approved plan id's included in this certificate:
Project Number: 38441 Type of construction: TRIMS Number: 78806 Classes of occupancy: 10 Name of Permit Holder: WEATHERSHIELD PTY LTD
Fit for occupancy or use pursuant S 53[3]
Endorsements:
•
The issue of this Certificate does not affect the limbility of a person to comply with the provisions of a haw of the Territory (including the Building Act) relating to the building work nor does it authorise the user of the land , contrary to a provision, convenant or condition of lease.
Deputy Building Controller Date
·



THE COURS

THE CADODIS

PART OF POORS

TO GUIRLO DOOR OPENERS

THE PROPERTY OF EVEL OF VICE A.C.T.

GARAGES CARPORTS GARDEN SHEDS FARM SHEDS


PHONE: 06 280 5654 1


E.O. ROX 2050 MANUKA ACT 2609


FACSIMILE: 06 239 1153


	DOODOSED CARACE EOR
	PROPOSED GARAGE FOR . Mrs P Sherpa
	BLOCK 8 SECTION 125
	SUBURB PALMERSTON
	PLANS/FILE No. 78% b/C. Received ACT Building Control (2 8 AUX 1335) ACT Government Service
SIDE ELEVATION (BOUNDARY SIDE)	REAR ELEVATION
·	METAL COLORBOND WALLS Beige
	METAL COLORBOND ROOF Beige
	THE TABLE COMMOND AS
W. PE Ref plan	2.206 Roller door
SIDE ELEVATION	FRONT ELEVATION
Approved Under Buildings (Design and Siting) Regulation 9 (Design From Public Notification  PLAN	LOO (FLATSHOS AND ENVIRONMENT) ACT 1951 (AS APPLIED)  PURCHANIT TIC SI CHION 230  Debruis  AUSTRALIAN CAPITAL TERRITORY PLANNING AUTHORITY



















END ELEVATION


SINGLE GARAGE 3050, 3650, 4270, 4800, WIDTHS






Proposed Garage <u>(Ur Mrs P Sherba</u> Block & Section 125 PALMERSTON






COLUMN FIXING TO SLAU

SPLICE DETAIL CULUMN





GIRT CONNECTION

PURLIN CONNECTION

## No es:

- CONCRETE STREAGTH FOR PARS 2010A

   CHEELWORK TO COURTY WHIT ACTIVITY \$ 1807

   ALL BOLTHOLES TO BE DREATH TO LARGE A HARD BOLTS

   ALL BELLWORK TO BE CITEAU AND COALED WITH

  BLUE BOUTH POPULE

- BLUE DRIVE PRICIENT.

   SINUCTURE DESIGNATION FOR WHITE CATEGORY 3 AF
  ALMIA AND LIVE LOAD OF 126 J.D.
   HETAL CLADDING FIXED WHITE 2 IS UNA 140 mm.
  GALV. CLOUTS, for manufactures specification.
- · CLADDING PROVIDES VERLICIAL DOS HIS TO STREETING, IF REMOVED PROVIDE 12 DIA. HOD VERT, PROSS BRACING
- TRUSSES ARE HOT DESIGNED IN CAPRY ADDITIONAL LOADS.

- \* ALL BOLTS TO BE GALVALUSED PURLINS AND GIRLS DY OF DOLLED WITH THE CUP HEAD BOLLS
- · BESTON PER EARTHQUAKE TODE TO AS 1111



Department of Urban Services

# ACT Building, Electrical and Plumbing Control

GPO Box 1908, Canberra ACT 2601

# Certificate of Occupancy and Use

Certificate No. 976276P1C1

This Certificate is issued in accordance with Section 53 (3) of the Building Act 1972.

The building work listed on this certificate has been completed substantially in accordance with the prescribed requirements and is considered fit for occupation and use.

ROSS MALCOLM TINDALE	Ske for Project  Address 8 LA TROBE CLOS	<b>E</b>	
Permit Number 976276P1	Suburb PALMERSTON	Section 125	Block 8
	Approved Plan 976276/A		
Building Work  Nature of Project Ilem Description	Unit Other Description	Class	of 😂 Type of

Nature of Work	Project Item Description (2)	Unit	7 %	Class of 🦃	Type of Construction
ADDITIONS TO	RESIDENCE			1a (i)	NA

# Comments

#### Important note:

- 1. Residential building statutory warranties and residential insurance apply in relation to building work.
- The issue, under this Part, of a certificate in respect of a building or portion of a building does not affect the liability of a person to comply with the provisions of a law of the Territory (including this Act) relating to the building or portion of the building.

STEPHEN-ELWORTHY E. MILNE


**Deputy Building Controller** 


1311 198

Date

Page 1 of 1

971210





CAMBERRA SEWERAGE AND WATER SUFFLY REGULATIONS Scale 15.22
All work must be corried out - academity with the Conbergo Sewerage and Water 2-ably Regulations PINTO HE'ES REFERENCE Block 8 SCHERTE: 18 URPTH: 1-1 COL: 20 54775; 30 0474; 07 04; 22, Tivohes 1 DAZO \$00 WATER DE CLOSE TROBE 7 1

Orainage Pic -: 56539

# PLAN OF SANITARY DRAINAGE


Section 125 PHIMERSTON

DESIGNED TO N.S.W. CODES OF PRACTICE

下 - 4 4 4 4 4 4 6 5 数字	•	FIXTURES:	,			_			LENNA!	SINK	_		
ENCE: Disconnector Trap Categoriem John Educt Version Educ		Ê	÷	4	٠,	4	vi	ç	_	, 2			
		REFERENCE:	Disconnector Trap	Expansion Joint	Shor Worls	Gully Trap	Inspection Chamber	napertion Opening	Inspection share	Janhole	Overflow Reflet Guily	son vent Pipe Japlositeised Polyvlay	Chaired Clay Dine

Designed by: BIRD MCNE-& PARTNERS Drown: LM Rr. D.2.25

44/45





18 September, 2013

Pamela Steele Sherpa PO Box 641 GUNGAHLIN ACT 2912

## TAX INVOICE/RECEIPT

Order number	Inspection Address	Date completed
213090751	8 La Trobe Close, Palmerston	17 September 2013
	Description of Services	Amount
	Standard Building, Pest Inspection and Compliance Report - includes GST	\$746.20
	Energy Report	\$0.00
-1-2014	ACTPLA Building File/Fees (GST free)	\$133.80
	Total:	\$880.00
6/9/2013	Payment received - thank you	\$880.00
We apprecia	te your business Balance:	\$0.00